



REV01-7/19

CT-1101 Assembly



PARTS				
PART	DESCRIPTION	PART NO.	QTY	
A	SIDE ASSEMBLY	SA-00299	2	
В	STOOL SPREADER	SS-11.25	4	
C	TABLE TOP ASSEMBLY 26"ROUND	SA-00300	1	




HARDWARE				
PART	DESCRIPTION	PART NO.	QTY	
а	#8 X 2" TORX SCREW	H-0000-S82	6	
b	#8 X 2-1/2" TORX SCREW	H-0000-S825	8	
С	T20 & T25 TORX BIT	H-0000-CTD	1	

Suggested Tools: Drill, Plastic Mallet

Please read entire instructions before beginning

1. Attach Part B to Part A using Hardware b



2. Place second Part A on assembled piece from Step 1,attach with Hardware b

